HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
ASPEN, CO		
ASPEN-PITKIN COUNTY /		
SARDY FIELD (ASE)	HS 1	Twy A2. Short taxi distance from ramp to rwy.
	HS 2	Twy A and west edge of ramp.
	HS 3	Twy A4. Short taxi distance from ramp to rwy.
DENVER, CO		
CENTENNIAL (APA)	HS 1	Int Twy A1. Hold line across run-up area.
	HS 2	Twy A, Twy A8, Twy A9 and Twy C1 congested intersections.
	HS 3	Twy C1 and Twy D1 close proximity to Rwy 10.
DENVER, CO		
ROCKY MOUNTAIN		
METROPOLITAN (BJC)	HS 1	Frequent helicopter operations.
EAGLE, CO		
EAGLE COUNTY RGNL (EGE)	HS 1	High density parking area.
CRAND HINCTION CO		
GRAND JUNCTION, CO GRAND JUNCTION RGNL (GJT)	HS 1	Rwy 22 and Rwy 29 close proximity, wrong rwy departure risk.

16 DEC 2010 to 13 JAN 2011

^{*}See appropriate A/FD, Alaska or Pacific Supplement HOT SPOT table for additional information.